


FIREBIRD



1969 (Only) Front Inner Fenders

Order (905) 850-3433 • Fax (905) 850-1722



1039ZA
Right

(New Part not list in 2009 Camaro/Firebird Catalog)

In Stock For February 2009

1039ZA	1969	RH Front Inner Fender
1039ZB	1969	LH Front Inner Fender

MSRP \$225.00 each

Visit us at www.goldenleafautomotive.com

Goldenleaf Automotive • 170 Zenway Blvd., Unit # 2, Woodbridge, Ontario, Canada, L4H 2Y7

FIREBIRD



1967-69 Radiator Support Gussets



Order (905) 850-3433 • Fax (905) 850-1722

(New Part not list in 2009 Camaro/Firebird Catalog)

In Stock For February 2009

1047ZB 1967-69 Radiator Support Gussets

MSRP \$54.00 pair

Visit us at www.goldenleafautomotive.com